



729 Third Avenue
Dallas, TX 75226

DW-1A


Display Warmer

Phone: (214) 421-7366
 Fax: (214) 565-0976
 Toll Free: (800) 527-2100
 Website: www.apwwyott.com
 E-mail: info@apwwyott.com

REPLACEMENT PARTS CATALOG & WIRING DIAGRAM

Model	P/N	Voltage / Wattage
DW-1A	75425	120V / 500W
DW-1A	75441	240V / 500W

Item	P/N	Description	Item	P/N	Description
1	75325	FRAME UPPER	12	89174	CLAMPING KNOB
2	75323	BASE ASSEMBLY	13	89182	HOLE BUSHING
3	75328	LAMP SHADE ASSEMBLY	14	75413	END CAP
4	75320	CORD COVER PLATE	15	89107	RUBBER FOOT
5	73003	PORCELAIN SOCKET	16	75421	WIRE SET
6	75410	LAMP P 120V/250W	Parts Not Shown		
7	66148	LAMP 240V/250W		88961	NUT 10-24 HEX GROUND
8	55956	CORDSET 120V		89039	SCREW 8-32 X 5/16 PH SL SS
9	55949	CORDSET 240V		89042	SCREW 8-32 X 1/2 PH SL SS
10	89476	WIRE NUT			
11	89101	STRAIN RELIEF BUSHING			






729 Third Avenue
Dallas, TX 75226



DW-1A

Display Warmer

Phone: (214) 421-7366
Fax: (214) 565-0976
Toll Free: (800) 527-2100
Website: www.apwwyott.com
E-mail: info@apwwyott.com

DW-1A WIRING DIAGRAM





ITEM	PART NUMBER	REQ'D	DESCRIPTION
1	75325-01	1	UPPER FRAME DW-IA WELD ASSEMBLY
2	75402	1	PLATE, SWITCH
3	75328	2	HEAT LAMP SHADE ASSY
4	89411	1	SWITCH, ON / OFF WITH WIRE LEADS
5	89101	1	BUSHING STRAIN RELIEF
6	55947	1	CORDSET 16GA SJTO NEMA 5-15P
7	89174	1	KNOB CLAMPING
8	89071	1	WASHER, #10 FLAT
9	88961	1	NUT, HEX 10-24, GREEN
10	75323	1	BASE ASSY DW-IA PLATED